

XA XCEL-ARC



RAZORWELD

TIG 200 AC/DC

XA-RZTIG200ACDCPFC | Operating Manual



1. Safety	3
2. Machine Features	7
3. Package Contents	8
4. Machine Specifications	9
5. Machine Layout	10
5.1 Front Panel Layout	10
5.2 Rear Panel Layout	10
6. Control Panel Layout	11
7. Control Panel Details	12
8. Weld Cycle Details	14
8.1 WELD CYCLE TERM GLOSSARY	15
8.2 AC TIG WELD CYCLE	16
8.3 DC TIG WELD CYCLE	17
8.4 MIX TIG WELD CYCLE	18
9. TIG: Machine Setup	19
10. TIG 200 AC/DC PFC Quick Setup Guide	22
11. TIG Welding Guide	23
12. MMA: Machine Setup	32
13. MMA: Welding Guide	35
15. TIG Troubleshooting	37
14. MMA (STICK) Troubleshooting	39
16. Factory Reset	40
17. Indicator Lights	40
18. Error Codes	41
19. ARC TORCHOLOGY® T3 TIG Torch	42

1. Safety

Welding and cutting equipment can be dangerous to both the operator and people in or near the surrounding working area if the equipment is not correctly operated. Equipment must only be used under the strict and comprehensive observance of all relevant safety regulations.

Read and understand this instruction manual carefully before the installation and operation of this equipment.

Machine operating safety

- Do not switch the function modes while the machine is operating. Switching of the function modes during welding can damage the machine. Damage caused in this manner will not be covered under warranty.
- Disconnect the electrode-holder cable from the machine before switching on the machine, to avoid arcing should the electrode be in contact with the workpiece.
- Operators should be trained and or qualified.



Electric shock: it can kill

- Touching live electrical parts can cause fatal shocks or severe burns. The electrode and work circuit is electrically live whenever the output is on. The input power circuit and internal machine circuits are also live when power is on. In MIG/MAG welding, the wire, drive rollers, wire feed housing, and all metal parts touching the welding wire are electrically live. Incorrectly installed or improperly grounded equipment is dangerous.
- Connect the primary input cable, according to Australian and New Zealand standards and regulations.
- Avoid all contact with live electrical parts of the welding/cutting circuit, electrodes and wires with bare hands.
- The operator must wear dry welding gloves while he/she performs the welding/cutting task.
- The operator should keep the workpiece insulated from himself/herself.
- Keep cords dry, free of oil and grease, and protected from hot metal and sparks.
- Frequently inspect input power cable for wear and tear, replace the cable immediately if damaged, bare wiring is dangerous and can kill.
- Do not use damaged, undersized, or badly joined cables.
- Do not drape cables over your body.
- We recommend (RCD) safety switch is used with this equipment to detect any leakage of current to earth.



Fumes and gases are dangerous

- Smoke and gas generated while welding or cutting can be harmful to people's health. Welding produces fumes and gases. Breathing these fumes and gases can be hazardous to your health.
- Do not breathe the smoke and gas generated while welding or cutting, keep your head out of the fumes.
- Keep the working area well ventilated, use fume extraction or ventilation to remove welding/cutting fumes and gases.
- In confined or heavy fume environments always wear an approved air-supplied respirator.
- Welding/cutting fumes and gases can displace air and lower the oxygen level, causing injury or death. Be sure the breathing air is safe.
- Do not weld/cut in locations near degreasing, cleaning, or spraying operations. The heat and rays of the arc can react with vapours to form highly toxic and irritating gases.
- Materials such as galvanised, lead, or cadmium plated steel, containing elements that can give off toxic fumes when welded/cut. Do not weld/cut these materials unless the area is very well ventilated, and or wearing an air-supplied respirator.



Arc rays: harmful to people's eyes and skin

- Arc rays from the welding/cutting process produce intense visible and invisible ultraviolet and infrared rays that can burn eyes and skin.
- Always wear a welding helmet with the correct shade of filter lens and suitable protective clothing, including welding gloves while the welding/cutting operation is performed.
- Measures should be taken to protect people in or near the surrounding working area. Use protective screens or barriers to protect others from flash, glare and sparks; warn others not to watch the arc.



Fire hazard

- Welding/cutting on closed containers, such as tanks, drums, or pipes, can cause them to explode. Flying sparks from the welding/cutting arc, hot workpiece, and hot equipment can cause fires and burns. Accidental contact of the electrode to metal objects can cause sparks, explosion, overheating, or fire. Check and be sure the area is safe before doing any welding/cutting.
- The welding/cutting sparks & spatter may cause fire, therefore remove any flammable materials well away from the working area. Cover flammable materials and containers with approved covers if unable to be moved from the welding/cutting area.
- Do not weld/cut on closed containers such as tanks, drums, or pipes, unless they are correctly prepared according to the required Safety Standards to ensure that flammable or toxic vapours and substances are totally removed, these can cause an explosion even though the vessel has been “cleaned”. Vent hollow castings or containers before heating, cutting or welding. They may explode.
- Do not weld/cut where the atmosphere may contain flammable dust, gas, or liquid vapours (such as petrol)
- Have a fire extinguisher nearby and know how to use it. Be alert that welding/cutting sparks and hot materials from welding/cutting can easily go through small cracks and openings to adjacent areas. Be aware that welding/cutting on a ceiling, floor, bulkhead, or partition can cause a fire on the hidden side.




Gas cylinders

- Shielding gas cylinders contain gas under high pressure. If damaged, a cylinder can explode. Because gas cylinders usually are part of the welding/cutting process, be sure to treat them carefully. CYLINDERS can explode if damaged.
- Protect gas cylinders from excessive heat, mechanical shocks, physical damage, slag, open flames, sparks, and arcs.
- Ensure cylinders are held secure and upright to prevent tipping or falling over.
- Never allow the welding/cutting electrode or earth clamp to touch the gas cylinder, do not drape welding cables over the cylinder.
- Never weld/cut on a pressurised gas cylinder, it will explode and kill you.
- Open the cylinder valve slowly and turn your face away from the cylinder outlet valve and gas regulator.



Gas build-up

- The build-up of gas can cause a toxic environment, deplete the oxygen content in the air resulting in death or injury. Many gases use in welding/cutting are invisible and odourless.
- Shut off shielding gas supply when not in use.
- Always ventilate confined spaces or use approved air-supplied respirator.



Electronic magnetic fields

- MAGNETIC FIELDS can affect Implanted Medical Devices.
- Wearers of Pacemakers and other Implanted Medical Devices should keep away.
- Implanted Medical Device wearers should consult their doctor and the device manufacturer before going near any electric welding, cutting or heating operation.



Noise can damage hearing

- Noise from some processes or equipment can damage hearing.
- Wear approved ear protection if noise level is high.



Hot parts

- Items being welded/cut generate and hold high heat and can cause severe burns.
- Do not touch hot parts with bare hands. Allow a cooling period before working on the welding/cutting gun. Use insulated welding gloves and clothing to handle hot parts and prevent burns.

Caution

Working environment

- The environment in which this welding/cutting equipment is installed must be free of grinding dust, corrosive chemicals, flammable gas or materials etc., and at no more than a maximum of 80% humidity.
- When using the machine outdoors, protect the machine from direct sunlight, rainwater and snow, etc.; the temperature of the working environment should be maintained within -10°C to +40°C.
- Keep this equipment 30cm distant from the wall.
- Ensure the working environment is well ventilated.

Safety tips

- **Ventilation:** This equipment is small-sized, compact in structure, and of excellent performance in amperage output. The fan is used to dissipate heat generated by this equipment during the welding/cutting operation. Important: Maintain good ventilation of the louvres of this equipment. The minimum distance between this equipment and any other objects in or near the working area should be 30 cm. Good ventilation is of critical importance for the normal performance and service life of this equipment.
- **Thermal Overload Protection:** Should the machine be used to an excessive level, or in a high-temperature environment, poorly ventilated area or if the fan malfunctions the Thermal Overload Switch will be activated, and the machine will cease to operate. Under this circumstance, leave the machine switched on to keep the built-in fan working to bring down the temperature inside the equipment. The machine will be ready for use again when the internal temperature reaches a safe level.
- **Over-Voltage Supply:** Regarding the power supply voltage range of the machine, please refer to the “Main parameter” table. This equipment is of automatic voltage compensation, which enables the maintaining of the voltage range within the given range. In case that the voltage of input power supply amperage exceeds the stipulated value, it is possible to cause damage to the components of this equipment. Please ensure your primary power supply is correct.
- Do not come into contact with the output terminals while the machine is in operation. An electric shock may occur.

Maintenance

Exposure to extremely dusty, damp, or corrosive air is damaging to the welding/cutting machine. To prevent any possible failure or fault of this welding/cutting equipment, clean the dust at regular intervals with clean and dry compressed air of required pressure.

Please note that: lack of maintenance can result in the cancellation of the guarantee; the guarantee of this welding/cutting equipment will be void if the machine has been modified, attempt to take apart the machine or open the factory-made sealing of the machine without the consent of an authorized representative of the manufacturer.

Troubleshooting

Caution: Only qualified technicians are authorized to undertake the repair of this welding/cutting equipment. For your safety and to avoid Electrical Shock, please observe all safety notes and precautions detailed in this manual.

Attention! - Check For Gas Leakage

At initial set up and at regular intervals we recommend to check for gas leakage

Recommended procedure is as follows:

1. Connect the regulator and gas hose assembly and tighten all connectors and clamps.
2. Slowly open the cylinder valve.
3. Set the flow rate on the regulator to approximately 8-10 L/min.
4. Close the cylinder valve and pay attention to the needle indicator of the contents pressure gauge on the regulator, if the needle drops away towards zero there is a gas leak. Sometimes a gas leak can be slow and to identify it will require leaving the gas pressure in the regulator and line for an extended time period. In this situation it is recommended to open the cylinder valve, set the flow rate to 8-10 L/min, close the cylinder valve and check after a minimum of 15 minutes.
5. If there is a gas loss then check all connectors and clamps for leakage by brushing or spraying with soapy water, bubbles will appear at the leakage point.
6. Tighten clamps or fittings to eliminate gas leakage.

IMPORTANT! - We strongly recommend that you check for gas leaks prior to operation of your machine. We recommend that you close the cylinder valve when the machine is not in use.

Esseti NZ Ltd, authorised representatives or agents of Esseti NZ Ltd will not be liable or responsible for the loss of any gas.

2. Machine Features



HD Backlit Interface

This next generation interface panel is bright and easy to read in any environment.

Power Factor Correction (PFC)

PFC gives you maximum electrical efficiency. It automatically compensates for any voltage fluctuation, and PFC is also designed to be generator friendly.

10A Plug

A 10 AMP power plug can be used on any domestic outlet. It's perfect for the DIY home handyman or the professional welder looking for a machine that can be used almost anywhere.

AC/DC

Weld every kind of metal. With the ability to run on an Alternating Current, you're able to weld aluminium as effortlessly as mild and stainless steels.

High Frequency TIG

Maximise your results from start to finish. A high-frequency torch can start an arc without contacting the workpiece, reducing the risk of contaminating the tungsten or the weld. It also means you get access to the entire TIG weld cycle, including pre- and post-gas and up and down slope parameters.

Multiple AC Waveforms

Completely customise your aluminium welds. Switch between Sine, Square, and Triangle waves to change the arc characteristics, bead profile, and penetration to suit your weld.

Mixed AC/DC

Experience the best of both worlds. Mixed AC/DC combines the efficiency of AC and the penetration of DC- TIG in one weld. With it, you get faster welding speeds, better penetration, a faster weld puddle on cold workpieces, and you can weld thicker materials.

Pulse TIG

Minimise the heat input without compromising on any of the penetration. Alternating between a peak and base current reduces the amount of heat input and focuses the arc, perfect for sheet metals and out-of-position welding.

Foot Control Ready

The perfect accessory, easily adjust your amperage to suit every weld as you go without disrupting your torch movement.

Smart Fan

Smart Fan diminishes noise, saves power, helps reduce energy costs, and minimises the number of contaminants being pulled through the machine.

Advanced MMA Features

The RAZORWELD TIG 200 AC/DC features adjustable Arc Force and Hot Start functionality. These features are designed for improving weld quality and ease of use.


Optional Remote Control

Upgrade your machine with a handy remote control. Both a wired and wireless controller are available.


3. Package Contents




RAZORWELD TIG 200 AC/DC




4m T3 TIG Torch




4m Electrode Holder



Argon Flowmeter



10A Plug Fitted



4m 300 AMP Earth Clamp

4. Machine Specifications

Technical Data

Parameter	Values
SKU	XA-RZTIG200ACDCPFC
Primary Input Voltage	240V Single Phase
Supply Plug	10 AMP
I _{eff} (A)	9.5
Rated Output	5A/20.8V - 200A/18V
No Load Voltage (V)	65v
Protection Class	IP23S
Insulation Class	H
Minimum Generator (kVA)	9.0
Dinse Connectors	35/50
Standard	AS/NZ60974-1
TIG Weld Material type	Aluminium, Magnesium, Zinc Alloys, Mild Steel, Stainless Steel, Copper, Silicon Bronze, Titanium
MMA Weld Material type	Mild Steel, Stainless Steel, Cast Iron
Warranty (Years)	5

TIG Specifications

Parameter	Values
TIG Arc Ignition Type	High Frequency, Lift Arc
TIG Process Type	Pulsed AC, Pulsed DC, Mixed AC/DC
DC TIG Welding Current Range	5-200A
AC TIG Welding Current Range	20-200A
TIG Duty Cycle @ 40°C	20% @ 200A 60% @ 115A 100% @ 90A
TIG Welding Thickness Range	1-8mm


STICK Specifications

Parameter	Values
STICK Welding Current Range	20-160A
STICK Duty Cycle @ 40°C	15% @ 160A 60% @ 80A 100% @ 62A
STICK Electrode Range	2.5-4.0mm
STICK Welding Thickness Range	2-10mm

Size & Weight


Parameter	Values
Dimensions (mm)	500×170×340 mm
Weight (kg)	11.7kg

5. Machine Layout



5.1 Front Panel Layout


1. Interface Panel
2. “+” Output Terminal
3. “-” Output Terminal
4. Gas Output to Torch
5. Wired Remote Connection Port
6. Wireless Remote Indicator



5.2 Rear Panel Layout

7. On/Off Switch
8. Gas Input
9. Water Cooler Power Port
10. Input Power Cord

6. Control Panel Layout



1. Numerical Display
2. Multi Function Adjustment Knob
3. Welding Mode Selection Button
4. TIG Start Type Button
5. Torch Mode Button
6. AC Wave Selection Button
7. TIG Pulse On/Off Button
8. MMA Settings Button
9. Remote Mode Button & Indicator
10. Water Cooler Button & Indicator
11. Weld Cycle Display Area
12. Warning Indicators (Overcurrent & Thermal Overload)
13. VRD Indicator Light

7. Control Panel Details

WELDING MODE SELECTION

AC TIG

AC TIG Mode

This indicates that the machine is in Alternating Current (AC) TIG mode.

When TIG welding in AC mode, the current supplied by the welding inverter operates with a positive and a negative half cycle. This means current flows in one polarity and then to the opposite polarity. The combination of one positive half cycle and one negative half cycle is termed one cycle. You will need to AC TIG Mode when welding aluminium.

DC TIG

DC TIG Mode

This indicates that the machine is in Direct Current (DC) TIG mode.

When TIG welding in DC mode the current supplied by the welding inverter operates within a single polarity. You will need this mode to weld most other metal types other than aluminium.

MIX TIG

MIX TIG Mode

This indicates that the machine is in Mixed AC/DC TIG mode.

Mixed AC/DC welding is the combination of TIG AC and TIG DC- in one weld. Mixed AC/DC gives you faster welding speeds, better penetration, and a faster weld puddle on cold workpieces. Mixed AC/DC is ideal when welding thicker aluminium.

MMA

MMA 'Stick' Mode

This indicates that the machine is in Manual Metal Arc mode.

TIG START SELECTION

HF TIG

High Frequency TIG Mode

This indicates that the machine will use High Frequency to start the weld arc while TIG welding. While using HF start, you do not need to touch the electrode to the workpiece, just press the trigger button on the torch or depress the foot pedal and the arc will start.

LIFT TIG

Lift Arc TIG Mode

This indicates that the machine will initiate the arc by lifting the electrode off of the workpiece.

TORCH MODE SELECTION

2T

2T Torch Mode

While in 2T mode, press and hold the torch trigger button to initiate the weld, and continue holding the trigger down during the duration of the desired weld.

4T

4T Torch Mode

While in 4T mode, press and release the torch trigger button to initiate the weld. To end the weld cycle, press and release the torch button again.

4TC

Circular 4T Torch Mode

4T Circular torch allows you to adjust your current on demand using the torch trigger.

While in 4TC mode, press and hold the torch trigger to initiate the weld at the **START AMP** value.

Releasing the trigger after its initial press will adjust your weld to the **PEAK AMP** value.

Pressing and holding the trigger again will adjust your weld to the **END AMP** value.

You can swap between **PEAK AMPS** and **END AMPS** as many times as desired.

Double press the trigger to end the weld cycle.

SPOT

Spot Mode

Create timed spot welds in intervals between 0.1 and 10 seconds.

(Cannot be used in conjunction with Pulse TIG mode)

AC WAVE SELECTION



Square Wave

While in square wave, the polarity switches instantly between EP (+) and EN (-). This allows for faster travel speeds and transfers a considerable amount of heat into the weld.



Triangle Wave

Triangle wave is ideal for thinner materials as it inputs the least amount of heat into the weld.



Sine Wave

Sine wave is the smoothest of the wave formats due to its gradual transition between EP and EN.

TIG PULSE MODE

PULSE ON/OFF

Pulse Mode

AC Pulse and DC Pulse add a secondary base amperage that the machine will oscillate to based on the settings chosen. Pulse TIG is great for heat management and also aids in out-of-position welding. Turning on Pulse mode enables the Base Amp, Pulse Width, and Pulse Hz settings for fine-tuning your pulsed weld cycle.

MMA SETTINGS

MMA AMP

Amperage Adjustment

When this indicator is lit you are in amperage adjustment mode. It functions for both MMA mode and Lift TIG mode.

HOT START

Hot Start

This indicates that you are adjusting the Hot Start parameter. Hot Start provides a boost of amperage at the beginning of the weld cycle, to help ignite the electrode. Hot Start can provide up to a 80 amp boost based upon your settings.

ARC FORCE

Arc Force

This indicates that you are adjusting the Arc Force parameter. Arc Force provides up to a 40 amp boost of your welding current to ensure optimum arc performance.

ANTI STICK

Anti-Stick

This unit has anti-stick functionality by default. If a short circuit occurs while welding for more than 2 seconds, the machine will automatically drop to 20A to allow the short circuit to be cleared. When the short circuit is cleared the welding current will automatically return to the set current.

8. Weld Cycle Details

To cycle through the Weld Cycle control, first press the control knob, then rotate in either direction to scroll through the various settings. Press the control knob again to enter that setting variable. The selected variable indicator will now begin to flash to indicate you can adjust that setting. After 5 seconds the system will revert back to the default parameter (Peak Amps).

8.1 WELD CYCLE TERM GLOSSARY

PRE GAS	This adjusts the amount of gas the torch will release after you have pressed the torch trigger and before the welding arc begins.
START AMP	This adjusts the amperage the weld cycle will begin with.
UP SLOPE	This adjusts the amount of ramp up time from Start Amp to Peak Amp.
PEAK AMP	This adjusts the amperage at the top of the weld cycle.
BASE AMP	This adjusts the amperage at the bottom of the pulse weld cycle. <i>(NOTE: Pulse Mode must be turned on)</i>
PULSE Hz	Pulse Hertz is the number of pulses (a cycle of Peak Amp and Base Amp) per second. A pulse Hz of 1.0 Hz would be one cycle of Peak Amp and Base Amp in 1 second. This setting is affected by AC Hz when welding in AC TIG mode. <i>(NOTE: Pulse Mode must be turned on)</i>
PULSE WIDTH	Pulse Width is the amount of time spent in the Peak Amps vs Base Amps for each pulse. If you set the percentage to 50%, that means 50% of the pulse cycle will be the Peak Amps, and 50% of the pulse will be the Base Amps. A setting of 90% would be 90% Peak Amps and 10% Base Amps. <i>(NOTE: Pulse Mode must be turned on)</i>
DOWN SLOPE	This adjusts the amount of ramp down time from Peak Amp to End Amp.
END AMP	This adjusts the amperage at the end of the weld cycle.
POST GAS	This adjusts the amount of gas the torch will release after the weld arc ends.
SPOT TIME	This adjusts the length of the spot weld. Ensure PULSE MODE IS OFF and SPOT MODE IS ON (using the Torch Mode Button). The machine will run a weld cycle of Pre Gas, Peak Amps for the selected time, and then Post Gas each time you press the torch trigger.
AC BALANCE	This adjusts the balance between Electrode Positive and Electrode Negative in the Alternating Current cycle. The EP portion of the AC cycle works to clean the oxidation layer, and the EN portion of the cycle deals with penetration of the workpiece. A setting of 20% would mean the cycle is 20% EP and 80% EN (less cleaning, more penetration). A setting of 60% would mean 60% EP and 40% EN (more cleaning, less penetration).
AC Hz	This adjusts the number of AC cycles to be completed in 1 second. A setting of 50 would mean the machine completes 50 AC cycles every second. <i>(NOTE: This affects Pulse Hz when active).</i>

WELD CYCLE TERM GLOSSARY CONTINUED


%
(MIX AC/DC)

This adjusts the balance between the mix of AC and DC- in the weld cycle. The % setting is based on the amount of DC you wish to balance. A setting of 40% would be 40% DC- and 60% AC.

Hz
(MIX AC/DC)


This adjusts the frequency of complete cycles between AC and DC-. Mixed AC/DC Hz is a calculation, and changes based on what the AC Hz is set to. It is recommended you first choose your AC Hz settings before adjusting your Mixed AC/DC Hz.

8.2 AC TIG WELD CYCLE




Parameter	Value Range
Pre Gas	0.0-3.0 Seconds
Start Amp	20-200 Amps
Up Slope	0.0-10.0 Seconds
Peak Amp	20-200 Amps
(When Active) Base Amp	20-200 Amps
(When Active) Pulse Hz	0.5-25 Hz (affected by AC Hz)
(When Active) Pulse Width	10-90%
Down Slope	0.0-10.0 Seconds
End Amp	20-200 Amps
Post Gas	0.0-15 Seconds
(When Active) Spot Time	0.1-10.0 Seconds
AC Balance	20-60%
AC Hz	20-250 Hz

8.3 DC TIG WELD CYCLE



Parameter	Value Range
Pre Gas	0.0-3.0 Seconds
Start Amp	5-200 Amps
Up Slope	0.0-10.0 Seconds
Peak Amp	20-200 Amps
(When Active) Base Amp	5-200 Amps
(When Active) Pulse Hz	0.5-200 Hz
(When Active) Pulse Width	10-90%
Down Slope	0.0-10.0 Seconds
End Amp	5-200 Amps
Post Gas	0.0-15 Seconds
(When Active) Spot Time	0.1-10.0 Seconds



8.4 MIX TIG WELD CYCLE




Parameter	Value Range
Pre Gas	0.0-3.0 Seconds
Start Amp	20-200 Amps
Up Slope	0.0-10.0 Seconds
Peak Amp	20-200 Amps
Down Slope	0.0-10.0 Seconds
End Amp	20-200 Amps
Post Gas	0.0-15 Seconds
AC Balance	20-60%
AC Hz	20-250 Hz
Mix AC/DC %	5-95%
Mix AC/DC Hz	1.0-25.0 Hz (affected by AC Hz)

9. TIG: Machine Setup


1. Connect the TIG torch to the **negative (-)** dinse connection, twist to lock in place. Then minding the Remote Wire Port grooves, plug in the remote cable and twist the end to secure the connection.
2. Push the gas connection hose into the gas outlet port until you hear a click which locks the hose in place.




3. Twist the earth clamp into the **positive (+)** dinse terminal of the machine.




4. Place argon flowmeter into the gas bottle outlet.




5. Tighten securely with wrench.




6. Connect gas hose to the flowmeter outlet using the twist nut to tighten the fitting securely.




7. Connect the other end of the gas hose to the gas inlet on the back of the machine.



8. Turn gas bottle on and twist the knob to adjust gas flow to 8-12L/min.




9. Connect the plug into a power point, then switch the machine ON.




10. Select the TIG process you wish to use and setup your weld cycle as desired.



11. Connect earth clamp to your workpiece.



12. Place your TIG torch near the workpiece and initiate an arc by pressing the trigger button on the TIG torch. (If HF mode is activated.)



10. TIG 200 AC/DC PFC Quick Setup Guide

AC TIG Setup (Aluminium TIG welding)

- **PRE-GAS:** 0.5 – 1 sec.
- **START AMPS:** 20A.
- **UP SLOPE:** 0.5 sec.
- **PEAK AMPS:** Depending on material thickness.
- **DOWN SLOPE:** 1.5 sec.
- **END AMPS:** 20A.
- **POST GAS:** 1 second to every 10Amps of Peak Current, E.g: 100 Amps = 10 Seconds.
Increase if tungsten is becoming black/dirty after welding. Post gas is required to ensure tungsten cools under gas coverage and does not oxidize.
- **AC BALANCE:** Start at 40% (balanced wave) and adjust to suit application.
- **AC HZ** (frequency): Start at 120Hz and adjust to suit application

DC TIG Setup

- **PRE-GAS:** 0.5 – 1 sec.
- **START AMPS:** 15A.
- **UP SLOPE:** 0.5 sec.
- **PEAK AMPS:** Depending on material thickness.
- **DOWN SLOPE:** 1.5 sec.
- **END AMPS:** 15A.
- **POST GAS:** 1 second to every 10Amps of Peak Current, E.g: 100 Amps = 10 Seconds.
Increase if tungsten is becoming black/dirty after welding. Post gas is required to ensure tungsten cools under gas coverage and does not oxidize.

Mix TIG Setup

- Same as AC TIG setup. See above.
- **Mix ACDC %:** Start at 50% and adjust to suit application.
- **Mix ACDC Hz** (frequency): 3Hz. Adjust to suit application.

MMA Setup

- **HOT START:** 30A to start with. Adjust to suit application.
- **ARC FORCE:** 10A to start with. Adjust to suit application.


11. TIG Welding Guide

DC TIG Welding

The DC power source uses what is known as DC (direct current), in which the main electrical component known as electrons flow in only one direction from the negative pole (terminal) to the positive pole (terminal). In the DC electrical circuit, there is an electrical principle at work which should always be taken into account when using any DC circuit. With a DC circuit, 70% of the energy (heat) is always on the positive side. This needs to be understood because it determines what terminal the TIG torch will be connected to (this rule applies to all the other forms of DC welding as well).

DC TIG welding is a process in which an arc is struck between a tungsten electrode and the metal workpiece. The weld area is shielded by an inert gas flow to prevent contamination of the tungsten, molten pool, and weld area. When the TIG arc is struck, the inert gas is ionised and superheated, changing its molecular structure, which converts it into a plasma stream. This plasma stream flowing between the tungsten and the workpiece is the TIG arc and can be as hot as 19,000°C. It is a very pure and concentrated arc which provides the controlled melting of most metals into a weld pool. TIG welding offers the user the highest amount of flexibility to weld the widest range of material thickness and types. DC TIG welding is also the cleanest weld with no sparks or spatter.

The intensity of the arc is proportional to the current that flows from the tungsten. The welder regulates the welding current to adjust the power of the arc. Typically, thin material requires a less powerful arc with less heat to melt the material, so less current (amps) is required. Thicker material requires a more powerful arc with more heat, so more current (amps) is necessary to melt the material.



High Frequency Arc Ignition for TIG (Tungsten Inert Gas) Welding

HF (High Frequency) ignition allows the arc to be started in TIG welding without touching the tungsten to the workpiece. By pressing the torch trigger the machine will activate the gas flow and introduce the HF spark, which "ionises" the air gap and makes it conductive, allowing an arc to be created without touching the tungsten to the workpiece. The gas molecules are superheated by the arc, creating a stream of super heated gas that changes the molecular structure into producing a plasma stream. This plasma stream provides heat and energy that allows us to melt and fuse metals in an inert gas shielded environment know as TIG (Tungsten Inert Gas) welding.

Pulse TIG Welding

Pulse TIG welding is when the current output (amperage) changes between a high and low current. Electronics within the welding machine create the pulse cycle. The high amperage is referred to as peak current, and the low amperage is referred to as base current. During pulse welding the weld pool cools during the low amperage period. This allows a lower overall heat input into the base metal. It allows for controlled heating and cooling periods during welding, providing better control of heat input, weld penetration, operator control and weld appearance.

There are 4 variables within the pulse cycle:

Peak Current - Base Current - Pulse Frequency - Pulse Width


Setting and manipulation of these variables will determine the nature of the weld current output and is at the discretion of the operator.

Peak Amp is the main welding current (amps) set to melt the material being welded and works much the same as setting maximum amperage values for regular DC TIG: as a general guide use 30-40 amps for every 1mm of material thickness.


Base Amp is the set level of background current (amps) which cools the weld puddle and effects overall heat input. As a rule, use enough background current to reduce the weld pool to about half its normal size while still keeping the weld pool fluid. As a guide start by setting the background amperage at 20 to 30 percent of peak amperage.

Pulse Hz is the number of pulses (a cycle of Peak Amp and Base Amp) per second. A pulse Hz of 1.0 Hz would be one cycle of Peak Amp and Base Amp in 1 second.

Pulse Width is the amount of time spent in the Peak Amps vs Base Amps for each pulse. If you set the percentage to 50%, that means 50% of the pulse cycle will be the Peak Amps, and 50% of the pulse will be the Base Amps. A setting of 90% would be 90% Peak Amps and 10% Base Amps.



Pulse TIG welding allows faster welding speeds with better control of the heat input into the job. Reducing the heat input, and minimising distortion and warping of the work is a particular advantage in the welding of thin stainless steel and carbon steel applications. The high pulse frequency capability of the advanced inverter agitates the weld puddle and allows you to move quickly without transferring too much heat to the surrounding metal. Pulsing also constricts and focuses the arc, increasing arc stability, penetration and travel speeds.




AC TIG Welding

It is possible with this machine to adjust the frequency of the AC cycle. That means that the amount of time it takes the AC wave to complete a full cycle switch from positive (+) to negative (-) can be adjusted from 20Hz (20 times per second) to 250Hz.


Increasing the frequency (Hz) causes the current to change direction more often, which means that it spends less time per cycle in both DC electrode negative and DC electrode positive mode. By spending less time at each polarity, the arc cone has less time to expand.

A higher frequency produces a narrower arc cone, which produces an arc that is tighter, with more focus at the exact spot the electrode is pointing. The result is improved arc stability, ideal for fillet welds and other fit ups requiring precise penetration. Decreasing the frequency softens the arc and broadens the weld pool, producing a wider bead, good overall penetration, and is ideal for build up applications.


AC Square Wave Hz




Slower AC Square Wave Hz




Faster AC Square Wave Hz



Slower AC Square Wave Hz



Faster AC Square Wave Hz




AC TIG Welding Further Details

AC (alternating current) enables us to TIG weld non ferrous alloys like Aluminium, Magnesium and Aluminium Alloys. These materials have an insulating surface oxide layer that melts at a higher temperature than the base metal making it difficult to weld the base metal if the oxides are not removed. AC welding current is ideal because the nature of the AC wave form assists in breaking the surface oxide layer.


AC (alternating current) has a current cycle that flows from + (direct) polarity to - (reverse) polarity.

The reversing of the polarity breaks the surface oxide while the direct polarity melts the base material.




There are inherent problems that come with AC TIG arc rectification, arc stutter, arc wandering and arc stoppage. These problems typically occur during the transition between + and - cycles.

The current is lesser (30%) during the half of the cycle when the electrode is positive and there is a resistance of the electron flow during this half cycle (rectification). The lack of current flow during this half cycle makes the AC arc unstable.




To overcome this lack of flow during one half of the cycle, a high-frequency (HF) voltage is generated and fed into the welding circuit. The HF maintains the arc stability during the half cycle when the electrode is positive.




High-frequency voltage flows continually in the welding circuit and keeps the shielding arc in the welding area in an ionized state. When the arc is ionized the arc is maintained during the half of the cycle when the electrode is positive. However while the arc is maintained less current flows during this half of the AC cycle, producing an unbalanced wave.


In older machines, a balanced current output wave was achieved using a large number of capacitors in series or a battery in the welding circuit. Modern TIG power sources use electronics to create and maintain a balanced wave and now most AC TIG power sources produce a square wave current output.




A square wave power supply can change the current from electrode + positive to electrode - negative very quickly. This produces high voltage as the current switches polarities allowing the arc to restart easily. The arc can be maintained without the use of high-frequency or any other arc stabilising methods.





BALANCED SQUARE WAVE FORM




The output current and voltage are controlled electronically so the balance between the amount of current electrode positive and the amount of current electrode negative can be adjusted. This allows the welder to adjust the amount of cleaning and the amount of penetration. This is achieved electronically by adjusting the balance control dial on the welding machine. More current flow from the + polarity produces stronger arc energy and current flow from the tungsten and is good for removing the oxidized surface of the work piece. However too much + current flow can drive too much energy to the tungsten causing it to overheat and melt the tungsten electrode.



Balance Adjusted for More Penetration - Cooler Tungsten




Balance Adjusted for More Oxide Cleansing Action - Hotter Tungsten




TIG Welding Fusion Technique

Manual TIG welding is often considered the most difficult of all the welding processes. Because the welder must maintain a short arc length, great care and skill are required to prevent contact between the electrode and the workpiece. Similar to Oxygen Acetylene torch welding, TIG welding typically requires two hands and in most instances requires the welder to manually feed a filler wire into the weld pool with one hand while manipulating the welding torch in the other. However, some welds combining thin materials can be accomplished without filler metal, such as edge, corner, and butt joints. This is known as Fusion welding where the edges of the metal pieces are melted together using only the heat and arc force generated by the TIG arc. Once the arc is started, the torch tungsten is held in place until a weld pool is created, a circular movement of the tungsten will assist in creating a weld pool of the desired size. Once the weld pool is established, tilt the torch at about a 75° angle and move smoothly and evenly along the joint while fusing the materials together.



TIG Welding with Filler Wire Technique


It is necessary for many situations with TIG welding to add a filler wire into the weld pool to build up weld reinforcement and create a strong weld. Once the arc is started, the torch tungsten is held in place until a weld pool is created, a circular movement of the tungsten will assist in creating a weld pool of the desired size. Once the weld pool is established, tilt the torch at about a 75° angle and move smoothly and evenly along the joint. The filler metal is introduced to the leading edge of the weld pool. The filler wire is usually held at about a 15° angle and fed into the leading edge of the molten pool. The arc will melt the filler wire into the weld pool as the torch is moved forward. Also, a dabbing technique can be used to control the amount of filler wire added. The wire is fed into the molten pool and retracted in a repeating sequence as the torch is moved slowly and evenly forward. It is essential during the welding to keep the molten end of the filler wire inside the gas shield as this protects the end of the wire from being oxidised and contaminating the weld pool.



Tungsten Preparation

Always use DIAMOND wheels when grinding and cutting, and be weary of breathing the dust created by the tungsten. While tungsten is a tough material, the surface of a diamond wheel is harder, and this makes for smooth grinding. Grinding without diamond wheels, such as aluminium oxide wheels, can lead to jagged edges, imperfections, or poor surface finishes not visible to the eye that will contribute to weld inconsistency and weld defects.

Always ensure to grind the tungsten in a longitudinal direction on the grinding wheel. Tungsten electrodes are manufactured with the molecular structure of the grain running lengthwise and thus grinding crosswise is "grinding against the grain." If electrodes are ground crosswise, the electrons have to jump across the grinding marks, and the arc can start before the tip and wander. Grinding longitudinally with the grain causes the electrons to flow steadily and easily to the end of the tungsten tip. The arc starts straight and remains narrow, concentrated, and stable.



Electrode Tip/Flat

The shape of the tungsten electrode tip is an important process variable in precision arc welding. A good selection of tip/flat size will balance the need for several advantages. The bigger the flat, the more likely arc wander will occur and the more difficult it will be to arc start. However, increasing the flat to the maximum level that still allows arc starts and eliminates arc wander will improve the weld penetration and increase the electrode life. Some welders still grind electrodes to a sharp point, which makes arc starting easier. However, they risk decreased welding performance from melting at the tip and the possibility of the point falling off into the weld pool.



Electrode Included Angle/Taper - DC

Tungsten electrodes for DC welding should be ground longitudinally and concentrically with diamond wheels to a specific included angle in conjunction with the tip/flat preparation. Different angles produce different arc shapes and offer different weld penetration capabilities. In general, blunter electrodes that have a larger included angle provide the following benefits:

- Last longer
- Have better weld penetration
- Have a narrower arc shape
- Can handle more amperage without eroding

Sharper electrodes with smaller included angle provide:

- Offer less arc weld
- Have a wider arc
- Have a more consistent arc

The included angle determines the weld bead shape and size. Generally, as the included angle increases, penetration increases and bead width decreases.



Tungsten Electrodes

- Tungsten is a rare metallic element used for manufacturing TIG welding electrodes. The TIG process relies on tungsten's hardness and high-temperature resistance to carry the welding current to the arc. Tungsten has the highest melting point of any metal, 3,410 degrees Celsius.
- Tungsten electrodes are non-consumable and come in a variety of sizes; they are made from pure tungsten or an alloy of tungsten and other rare earth elements. Choosing the correct tungsten depends on the material being welded, the number of amps required and whether you are using AC or DC welding current.
- Tungsten electrodes are colour-coded at the end for easy identification.
- Below are the most commonly used tungsten electrodes found in the New Zealand and Australian market.

Thoriated

Thoriated tungsten electrodes (AWS classification EWTh-2) contain a minimum of 97.30 per cent tungsten and 1.70 to 2.20 per cent thorium and are called 2 per cent thoriated. They are the most commonly used electrodes today and are preferred for their longevity and ease of use. Thorium, however, is a low-level radioactive hazard and many users have switched to other alternatives. Regarding the radioactivity, thorium is an alpha emitter, but when it is enclosed in a tungsten matrix, the risks are negligible. Thoriated tungsten should not get in contact with open cuts or wounds. The more significant danger to welders can occur when thorium oxide gets into the lungs. This can happen from the exposure to vapours during welding or ingestion of material/dust in the grinding of the tungsten. Follow the manufacturer's warnings, instructions, and the Material Safety Data Sheet (MSDS) for its use.

E3 (Colour Code: Turquoise)

E3 tungsten electrodes (AWS classification EWG) contain a minimum of 98% percent tungsten and up to 1.5 percent Lanthanum and small percentages of Zirconium and Yttrium they are called E3 Tungsten. E3 Tungsten Electrodes provide conductivity similar to that of thoriated electrodes. Typically, this means that E3 Tungsten Electrodes are exchangeable with thoriated electrodes without requiring significant welding process changes. E3 deliver superior arc starting, electrode lifetime, and overall cost-effectiveness. When E3 Tungsten Electrodes are compared with 2% thoriated tungsten, E3 requires fewer re-grinds and provides a longer overall lifetime. Tests have shown that ignition delay with E3 Tungsten Electrodes actually improves over time, while 2% thoriated tungsten starts to deteriorate after only 25 starts. At equivalent energy output, E3 Tungsten Electrodes run cooler than 2% thoriated tungsten, thereby extending overall tip lifetime. E3 Tungsten Electrodes work well on AC or DC. They can be used DC electrode positive or negative with a pointed end, or balled for use with AC power sources.

Ceriated (Colour Code: Grey)

Ceriated tungsten electrodes (AWS classification EWCe-2) contain a minimum of 97.30 per cent tungsten and 1.80 to 2.20 per cent cerium and are referred to as 2 per cent ceriated. Ceriated tungstens perform best in DC welding at low current settings. They have excellent arc starts at low amperages and become popular in such applications as orbital tube welding, thin sheet metal work. They are best used to weld carbon steel, stainless steel, nickel alloys, and titanium, and in some cases, it can replace 2 per cent thoriated electrodes. Ceriated tungsten is best suited for lower amperages it should last longer than Thoriated tungsten higher amperage applications are best left to Thoriated or Lanthanated tungsten.






Lanthanated (Colour Code: Gold)

Lanthanated tungsten electrodes (AWS classification EWL-1.5) contain a minimum of 97.80 per cent tungsten and 1.30 per cent to 1.70 per cent lanthanum and are known as 1.5 per cent lanthanated. These electrodes have excellent arc starting, a low burn-off rate, good arc stability, and excellent re-ignition characteristics. Lanthanated tungstens also share the conductivity characteristics of 2 per cent thoriated tungsten. Lanthanated tungsten electrodes are ideal if you want to optimise your welding capabilities. They work well on AC or DC electrode negative with a pointed end, or they can be balled for use with AC sine wave power sources. Lanthanated tungsten maintains a sharpened point well, which is an advantage for welding steel and stainless steel on DC or AC from square wave power sources.

Zirconiated (Colour Code: White)

Zirconiated tungsten electrodes (AWS classification EWZr-1) contain a minimum of 99.10 per cent tungsten and 0.15 to 0.40 per cent zirconium. Most commonly used for AC welding Zirconiated tungsten produces a very stable arc and is resistant to tungsten spitting. It is ideal for AC welding because it retains a balled tip and has a high resistance to contamination. Its current-carrying capacity is equal to or greater than that of thoriated tungsten. Zirconiated tungsten is not recommended for DC welding.

11.1 TIG Tungsten Selection Guide

	 LANTHANATED (GOLD)	 ZIRCONIATED (WHITE)	 THORIATED (RED)	 E3 (TURQUOISE)	 CERIATED (GREY)
AC CURRENT	✓	✓		✓	✓
DC CURRENT	✓		✓	✓	✓
ALUMINIUM	✓	✓		✓	✓
MILD STEEL	✓		✓	✓	✓
STAINLESS STEEL	✓		✓	✓	✓
TITANIUM / COPPER ALLOYS	✓		✓	✓	✓
ARC IGNITION	●●●●●	●●●●●	●●●●●	●●●●●	●●●●●
TUNGSTEN LIFE	●●●●●	●●●●●	●●●●●	●●●●●	●●●●●
ARC STABILITY	●●●●●	●●●●●	●●●●●	●●●●●	●●●●●
RESISTANCE TO CONTAMINATION	●●●●●	●●●●●	●●●●●	●●●●●	●●●●●
AC PERFORMANCE	●●●●●	●●●●●	N/A	●●●●●	●●●●●



This information is intended to act as a guide only, individual results may vary depending on technique, skill and material.

11.2 Tungsten Electrodes Rating for Welding Currents


Tungsten Diameter (mm)	Diameter at the Tip (mm)	Constant Included Angle (°)	Current Range (Amps)	Current Range (Pulsed Amps)
1.0mm	0.25	20	5 - 30	5 - 60
1.6mm	0.5	25	8 - 50	5 - 100
1.6mm	0.8	30	10 - 70	10 - 140
2.4mm	0.8	35	12 - 90	12 - 180
2.4mm	1.1	45	15 - 150	15 - 250
3.2mm	1.1	60	20 - 200	20 - 300
3.2mm	1.5	90	25 - 250	25 - 350

12. MMA: Machine Setup


1. For DC+ electrodes, connect earth clamp to the **negative (-)** dinse connection, and electrode holder to the **positive (+)** dinse connection.
2. For DC- electrodes, connect earth clamp to the **positive (+)** dinse connection, and electrode holder to the **negative (-)** dinse connection.




3. Connect the plug into a power point, then switch the machine ON.
4. Ensure that MMA mode is activated on the front panel by pressing the **WELD MODE** button.




5. Twist electrode holder to loosen grip.



6. Place electrode into electrode holder.



7. Twist electrode holder to tighten and securely grip electrode.




8. Using the adjustment knob, select the amperage according to the size of your chosen electrode and workpiece.




9. Using the MMA settings button, adjust the Hot Start and Arc Force settings as desired.




10. Connect earth clamp to your workpiece.



11. Strike electrode to the workpiece to initiate arc.




12. Drag along workpiece to weld. Pull the electrode away from the workpiece to finish weld.



13. MMA: Welding Guide

One of the most common types of arc welding is Manual Metal Arc welding, also known as MMA welding. An electric current is used to strike an arc between the base material and a consumable electrode rod or 'stick'. The electrode rod is made of a material that is compatible with the base material being welded. They are covered with a flux that gives off gaseous vapours that serve as a shielding gas and provide a layer of slag, both of which protect the weld area from atmospheric contamination. The electrode core itself acts as filler material. The residue from the flux that forms a slag covering over the weld metal must be chipped away after welding.



- The arc is initiated by momentarily touching the electrode to the base metal.
- The heat of the arc melts the surface of the base metal to form a molten pool at the end of the electrode.
- The melted electrode metal is transferred across the arc into the molten pool and becomes the deposited weld metal.
- The deposit is covered and protected by a slag which comes from the electrode coating.
- The arc and the immediate area are enveloped by an atmosphere of protective gas.

Manual Metal Arc (stick) electrodes have a solid metal wire core and a flux coating. These electrodes are identified by the wire diameter and by a series of letters and numbers. The letters and numbers identify the metal alloy and the intended use of the electrode.

The metal wire core works as a conductor of the current that maintains the arc. The core wire melts and is deposited into the welding pool.

The covering on a shielded metal arc welding electrode is called flux. The flux on the electrode performs many different functions.

These include:

- Producing a protective gas around the weld area.
- Providing fluxing elements and de-oxidisers.
- Creating a protective slag coating over the weld as it cools.
- Establishing arc characteristics.
- Adding alloying elements.

Covered electrodes serve many purposes in addition to adding filler metal to the molten pool. These additional functions are provided mainly by the covering on the electrode.

Electrode Selection

As a general rule, the selection of an electrode is straight forward, in that it is only a matter of selecting an electrode of similar composition to the parent metal. However, for some metals, there is a choice of several electrodes, each of which has particular properties to suit specific classes of work.

The size of the electrode generally depends on the thickness of the section being welded, and the thicker the section, the larger the electrode required. The table gives the maximum size of electrodes that may be used for various thicknesses of section based on using a general-purpose type 6013 electrode.

Average Thickness of Material	Maximum Recommended Electrode Diameter
1.0 - 2.0mm	2.5mm
2.0 - 5.0mm	3.2mm
> 5.0mm	4.0mm

Correct current selection for a particular job is an important factor in arc welding. With the current set too low, it is difficult to strike and maintain a stable arc. The penetration is reduced and beads with a distinct rounded profile will be deposited. Too high a current is accompanied by overheating of the electrode, resulting in undercut, burning through of the base metal and producing excessive spatter.

Electrode Size (ø mm)	Current Range (Amps)
2.5mm	60 - 100
3.2mm	90 - 150
4.0mm	140 - 200

Arc Length

To strike the arc, the electrode should be gently scraped on the work until the arc is established. There is a simple rule for the proper arc length; it should be the shortest arc that gives a good surface to the weld. An arc too long reduces penetration, produces spatter and gives a rough surface finish to the weld. An excessively short arc will cause sticking of the electrode and result in poor quality welds. The general rule of thumb for down hand welding is to have an arc length no greater than the diameter of the core wire.

Electrode Angle

The angle that the electrode makes with the work is important to ensure a smooth, even transfer of metal. When welding in down hand, fillet, horizontal or overhead, the angle of the electrode is generally between 5 and 15 degrees towards the direction of travel. When vertical up welding, the angle of the electrode should be between 80 and 90 degrees to the workpiece.

Travel Speed

The electrode should be moved along in the direction of the joint being welded at a speed that will give the size of run required. At the same time, the electrode is fed downwards to keep the correct arc length at all times. Excessive travel speeds lead to poor fusion, lack of penetration, etc., while too slow a rate of travel will frequently lead to arc instability, slag inclusions and poor mechanical properties.

Material and Joint Preparation

The material to be welded should be clean and free of any moisture, paint, oil, grease, mill scale, rust or any other material that will hinder the arc and contaminate the weld material. Joint preparation will depend on the method used include sawing, punching, shearing, machining, flame cutting and others. In all cases, edges should be clean and free of any contaminates. The chosen application will determine the type of joint.

15. TIG Troubleshooting

15.1 Tungsten burning away quickly

- **Incorrect gas or no gas:** Use pure argon. Check cylinder has gas, connected, turned on, and torch valve is open.
- **Inadequate gas flow:** Check the gas is connected, check hoses, gas valve and torch are not restricted.
- **Back cap not fitted correctly:** Make sure the torch back cap is fitted so that the O-ring is inside the torch body.
- **Torch connected to DC+:** Connect the torch to the DC- output terminal.
- **Incorrect tungsten being used:** Check and change the tungsten type if necessary.
- **Tungsten being oxidised after weld is finished:** Keep shielding gas flowing 10-15 seconds after arc stoppage.

15.2 Contaminated tungsten

- **Touching tungsten into the weld pool:** Keep tungsten from contacting weld puddle. Raise the torch so that the tungsten is off of the work piece 2-5mm.
- **Touching the filler wire to the tungsten:** Keep the filler wire from touching the tungsten during welding, feed the filler wire into the leading edge of the weld pool in front of the tungsten.
- **Not enough post gas:** Tungsten oxidizing due to being cooled by air not by gas. Increase post gas

15.3 Porosity - Poor weld appearance and colour

- **Wrong gas / poor gas flow / gas leaks:** Use pure argon. Gas is connected, check hoses, gas valve and torch are not restricted. Set the gas flow between 8-12 L/min. Check hoses and fittings for holes, leaks etc.
- **Contaminated base metal:** Remove moisture and materials like paint, grease, oil, and dirt from base metal.
- **Contaminated filler wire:** Remove all grease, oil, or moisture from filler metal.
- **Incorrect filler wire:** Check the filler wire and change if necessary.

15.4 Yellowish residue/smoke on the alumina nozzle & discoloured tungsten

- **Incorrect gas:** Use pure argon gas.
- **Inadequate gas flow:** Set the gas flow between 8-12 L/min flow rate.
- **Alumina gas nozzle too small:** Increase the size of the alumina gas nozzle.

15.5 Unstable arc during welding

- **Torch connected to DC+:** Connect the torch to the DC- output terminal.
- **Contaminated base metal:** Remove materials like paint, grease, oil, and dirt, including mill scale from base metal.
- **Tungsten is contaminated:** Remove 10mm of contaminated tungsten and re-grind the tungsten.
- **Arc length too long:** Lower torch so that the tungsten is off of the work piece 2-5mm.

15.6 Arc wanders during welding

- **Poor gas flow:** Check and set the gas flow between 8-12 L/min flow rate.
- **Amperage too low:** Increase the amperage.
- **Incorrect arc length:** Lower torch so that the tungsten is off of the work piece 2-5mm.
- **Tungsten incorrect or in poor condition:** Check that correct type of tungsten is being used. Remove 10mm from the weld end of the tungsten and re-sharpen the tungsten.
- **Poorly prepared tungsten:** Grind marks should run lengthwise with tungsten, not circular. Use proper grinding method and wheel.
- **Contaminated base metal or filler wire:** Remove contaminating materials like paint, grease, oil, and dirt, including mill scale, from base metal. Remove all grease, oil, or moisture from filler metal.

15.7 Arc difficult to start or will not start welding

- **Incorrect machine set up:** Check machine set up is correct.
- **No gas, incorrect gas flow:** Check the gas is connected and cylinder valve open, check hoses, gas valve and torch are not restricted. Set the gas flow between 8-12 L/min flow rate.
- **Incorrect tungsten size or type:** Check and change the size and or the tungsten if required.
- **Loose connection:** Check all connectors and tighten.
- **Earth clamp not connected to work:** Connect the earth clamp directly to the workpiece wherever possible.

14. MMA (STICK) Troubleshooting

14.1 No arc

- **Incomplete welding circuit:** Check earth lead is connected. Check all cable connections.
- **Wrong mode selected:** Check the MMA selector switch is selected.
- **No power supply:** Check that the machine is switched on and has a power supply.

14.2 Porosity - Small cavities or holes resulting from gas pockets in weld metal

- **Arc length too long:** Shorten the arc length.
- **Workpiece dirty, contaminated or moisture:** Remove moisture and materials like paint, grease, oil, and dirt, including mill scale, from base metal.
- **Damp electrodes:** Use only dry electrodes.

14.3 Excessive spatter

- **Amperage too high:** Decrease the amperage or choose a smaller electrode.
- **Arc length too long:** Shorten the arc length.

14.4 Weld sits on top, lack of fusion

- **Insufficient heat input:** Increase the amperage or choose a smaller electrode.
- **Workpiece dirty, contaminated or moisture:** Remove moisture and materials like paint, grease, oil, and dirt, including mill scale, from base metal.
- **Poor welding technique:** Use the correct welding technique or seek assistance for the correct technique.

14.5 Lack of penetration

- **Insufficient heat input:** Increase the amperage or choose a smaller electrode.
- **Poor welding technique:** Use the correct welding technique or seek assistance for the correct technique.
- **Poor joint preparation:** Check the joint design and fit up, make sure the material is not too thick. Seek assistance for the correct joint design and fit up.

14.6 Excessive penetration - Burn through

- **Excessive heat input:** Reduce the amperage or use a larger electrode.
- **Incorrect travel speed:** Try increasing the weld travel speed.

14.7 Uneven weld appearance

- **Unsteady hand, wavering hand:** Use two hands where possible to steady up, practise your technique.

14.8 Distortion - Movement of base metal during welding

- **Excessive heat input:** Reduce the amperage or use a larger electrode.
- **Poor welding technique:** Use the correct welding technique or seek assistance for the correct technique.
- **Poor joint preparation and/or joint design:** Check the joint design and fit up, make sure the material is not too thick. Seek assistance for the correct joint design and fit up.

14.9 Electrode welds with different or unusual arc characteristic

- **Incorrect polarity:** Change the polarity, check the electrode manufacturer for correct polarity.

16. Factory Reset

If you wish to reset the machine to factory settings, **press and hold the Welding Mode Selection Button for 5 seconds** to restore factory settings.

After pressing and holding for 5 seconds, the display window will count down from 3. When the countdown ends, the factory settings are restored. If the button is released before the countdown ends, the factory restore will not take place.

WARNING THIS CANNOT BE UNDONE

17. Indicator Lights



THERMAL OVERLOAD

Typically caused by duty cycle limits. **DO NOT POWER OFF MACHINE.** Wait for the machine to cool down and for indicator to turn off before welding again.



OVERCURRENT LIMIT

Typically caused by internal fault of machine. Restart machine and attempt to weld again. If problem persists contact Xcel-Arc Service Support.



VRD - NORMAL - ABNORMAL

Voltage Reduction Device is a safety feature for MMA welding. If this indicator turns red restart the machine. If it persists contact Xcel-Arc Service Support.


WARNING: There are extremely dangerous voltage and power levels present inside this unit. Do not attempt to diagnose or repair unit by removing external cover unless you are an authorised repair agent for Xcel-Arc.

18. Error Codes

Error Code	Issue	Details
E10	Overcurrent Protection	The machine is outputting more current than it is rated for. This is likely due to internal fault.
<i>Possible Solution: Power down and restart machine.</i>		
E31	Under Voltage Protection	Voltage source for machine is too low. This is likely caused by an extension cable.
<i>Possible Solution: Remove any extension cables and check power socket and machine power wire. Attempt weld on a different power circuit.</i>		
E32	Over Voltage Protection	Voltage source for machine is too high.
<i>Possible Solution: Remove any extension cables and check power socket and machine power wire. Attempt weld on a different power circuit.</i>		
E55	Data Error Alarm	Issue with internal memory chip.
<i>Possible Solution: Power down and restart machine.</i>		
E60	Rectifier Overheat	Internal temperature is too high. This is likely caused by reaching duty cycle limit.
<i>DO NOT TURN OFF MACHINE! Wait for machine to cool down and for indicator warning to turn off.</i>		
E61	IGBT Overheat	Internal temperature is too high. This is likely caused by reaching duty cycle limit.
<i>DO NOT TURN OFF MACHINE! Wait for machine to cool down and for indicator warning to turn off.</i>		
E71	Water Tank Alarm	Low coolant level in water cooler.
<i>Possible Solution: Refill water cooler and restart machine after checking all cable connections.</i>		
RED VRD ICON	Abnormal VRD	The No-Load voltage is too high. This is likely caused by VRD fault.
<i>Possible Solution: Power down and restart machine.</i>		

After attempting the possible solutions listed in the chart above please contact Xcel-Arc Support Services if you are still experiencing issues with your machine.

19. ARC TORCHOLOGY® T3 TIG Torch



T3 TIG TORCH 240 AMP AIR COOLED

Rating: 240A DC, 170A AC @35% duty cycle.

Torch Model

Description	Part Number 4m	8m
ARC T3Tig Torch 35-50 Twistlok End, QF Gas	ARC-T3-4M	ARC-T3-8M
ARC T3FX Flexi Tig Torch 35-50 Twistlok End, QF Gas	ARC-T3FX-4M	ARC-T3FX-8M

Spare Parts


Part Number	Description
1	T3GS Head Gasket
2	T3SN Heat Zone Isolator
3	T3QZSN23 Quartz Heat Zone Isolator
4	AT2601 T3 Torch Body Air-Cooled
	AT2601F T3 Flexible Torch Body Air-Cooled
5	T3LBC Long Back Cap
6	T3MBC Medium Back Cap
7	T3SBC Short Back Cap
8*	ATER1MS Momentary Switch Kit
9	ATERH200 Arc Handle Kit
10	ATERSP1 Screw Pack
11	ATERSWL4 Trigger Lead 4m
	ATERSWL8 Trigger Lead 8m
12	ATHS18MM-90 Heat Shrink Tube
13	ATERKJ200 Knuckle Joint
14	ATERLC200-08 Leather Cover x 0.8m
15	ATERJK200 Joint Repair Kit

Spare Parts

Part Number	Description
16	ATERNCL-32 Neoprene Cover Assembly x 3.2m
	ATERNCL-72 Neoprene Cover Assembly x 7.2m
17	ATERCO200-40 Sheath x 4m Inc Leather Cover
	ATERCO200-80 Sheath x 8m Inc Leather Cover
18	ATSLH26-S Cable Support Large
19	ATSLH26-C Surelok™ Housing Cover
20	ATNSLH26-H Surelok™ Housing Large
21	AT2620-4M-OB Power Cable x 4m Surelok O/B Rubber
	AT2620-8M-OB Power Cable x 8m Surelok O/B Rubber
22	ATNSL3550 Surelok Body & Support
23	ATNSLOB-1-GS# Gas Supply Hose O/B
24	AT-SP Spanner

19.1 T3 TIG Torch Consumables

Gas Lens Body Starter Kits - Medium




Part #	Description
MGL2	ARC Medium Gas Lens Body Starter Kit 1.6mm Ø
MGL4	ARC Medium Gas Lens Body Starter Kit 2.4mm Ø
MGL5	ARC Medium Gas Lens Body Starter Kit 3.2mm Ø


Front End Wear Parts - Medium



Part #	Description	Size
T3CC04	Ceramic Cup Ø6mm	4
T3CC05	Ceramic Cup Ø8mm	5
T3CC06	Ceramic Cup Ø10mm	6
T3CC07	Ceramic Cup Ø11mm	7
T3CC08	Ceramic Cup Ø12.5mm	8
T3CC10	Ceramic Cup Ø16mm	10
T3CC12	Ceramic Cup Ø19mm	12



Part #	Description
T3GL10	Gas Lens Collet Body 1.0mm
T3GL16	Gas Lens Collet Body 1.6mm
T3GL24	Gas Lens Collet Body 2.4mm
T3GL32	Gas Lens Collet Body 3.2mm



Part #	Description
T3CB10	Collet Body 1.0mm
T3CB16	Collet Body 1.6mm
T3CB24	Collet Body 2.4mm
T3CB32	Collet Body 3.2mm

Standard Quartz series



Part #	Description	Size
T3QZ06	ARC T3/T5W Standard Quartz Cup 10mm Bore	6
T3QZ08	ARC T3/T5W Standard Quartz Cup 12mm Bore	8
T3QZ10	ARC T3/T5W Standard Quartz Cup 15mm Bore	10
T3QZ12	ARC T3/T5W Standard Quartz Cup 20mm Bore	12

Gas Lens Body Filter Kits - Medium



Part #	Description
MGL10FS-3KIT	ARC Medium Gas Lens Body Filter Kit-1.0mm Ø (3 per Kit)
MGL16FS-3KIT	ARC Medium Gas Lens Body Filter Kit-1.6mm Ø (3 per Kit)
MGL24FS-3KIT	ARC Medium Gas Lens Body Filter Kit-2.4mm Ø (3 per Kit)
MGL32FS-3KIT	ARC Medium Gas Lens Body Filter Kit-3.2mm Ø (3 per Kit)

Back Caps



Part #	Description
T3SBC	ARC T3 Short Back Cap
T3MBC	ARC T3 Medium Back Cap
T3LBC	ARC T3 Long Back Cap

Head Gasket & Isoator



Part #	Description
T3GS	ARC T3 Head Gasket
T3SN	ARC T3 Heat Zone Isolator
T3QZSN23	ARC T3 Quartz Heat Zone Isolator



Esseti New Zealand Limited

PO Box 4189, Palmerston North - 4442

Phone: 06 355 1103

Fax: (06) 354 2437

Email: sales@esseti.co.nz

www.esseti.co.nz